ECHNICAL INFORMATION

Trakita

A6980 P 1/1


► Change of Spur gear 51 and Driving flange Elimination of Pin 6 and Flat washer 30

December 2014

▶ BHR242, BHR243, DHR242, DHR243, HR2300, HR2310T, HR2600, HR2601, HR2610, HR2610T, HR2611F, HR2611FT, HR2621, LXRH01, LXRH02, XRH01, XRH02

All countries

- Description To improve the durability of Spur gear 51:
 - Spur gear 51 and Driving flange have been changed.
 - Pin 6 (6 pcs.) and Flat washer 30 have been eliminated. See below for the details.



	Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note	
1		Spur gear 51 227232-6	1	No	Spur gear 51 227360-7	1	Interchangeable as a set	
2		Driving flange 313149-0	1	No	Driving flange 332139-4	1		
3		Flat washer 30 267414-8	1					
4		Pin 6 268226-2	6				↓ ↓	

1	2	3	4
032	031	034	033
032	031	034	033
032	031	034	033
032	031	034	033
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
030	029	032	031
032	031	034	033
032	031	034	033
032	031	034	033
032	031	034	033
	032 032 032 030 030 030 030 030 030 030	032 031 032 031 032 031 032 031 030 029 030 029 030 029 030 029 030 029 030 029 030 029 030 029 030 029 030 029	032 031 034 032 031 034 032 031 034 032 031 034 030 029 032 030 029 032

From February 2015 production

